From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:55 AM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 156 Queens smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, October 10, 2013 10:17 AM

To: Gorman, John

Subject: P.S. 156 Queens smoking ballast incident

John,

P.S. 156 located at 229 - 07 137th Avenue in Queens had a visibly smoking ballast in office200A this morning 10/10. The room was immediately secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:55 AM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 57 Manhattan smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, October 10, 2013 10:08 AM

To: Gorman, John

Subject: P.S. 57 Manhattan smoking ballast incident

John,

P.S. 57 located at 176 East 115th Street in Manhattan had a visibly smoking ballast in room 228 this morning 10/10. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano


Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101



From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:55 AM

То:

Haklar, James; Molnar, William; Santella, Dennis; Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 157 Bronx external leak

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, October 09, 2013 11:54 AM

To: Gorman, John

Subject: RE: P.S. 157 Bronx external leak

John.

As a follow up to my previous email, the impacted floor was cleaned by our environmental contractor and 5 wipe samples were taken from room 224. All wipe sample results are below the detection limit. Room 224 will be reoccupied. Parent notification letters will be sent.

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, October 08, 2013 11:59 AM
To: 'Gorman, John' (Gorman, John@epa.gov)
Subject: P.S. 157 Bronx external leak

Good morning John:

P.S. 157 located at 757 Caldwell Avenue in the Bronx reported a burning odor from a light fixture in room 224 on Thursday 10/3. The room was immediately evacuated and secured. Our environmental contractor inspected the light fixtures in the room and found 6 leaking PCB ballasts. All ballasts and fixtures were removed Thursday evening. Prior to re-occupancy, the custodian noticed dried pieces of a tar like substance on the floor and a student's desk. Our environmental contractor re-inspected the room last night and confirmed that the tar may contain PCB's. The environmental contractor disposed of the impacted student desk as PCB contaminated waste and cleaned the impacted floor using Capsur. Our environmental consultant will take wipe samples of the impacted floor today. The room will remain closed until favorable wipe results are returned. Parental notification letters were sent.

Let me know if you have any questions.

Regards, Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:55 AM

To:

Haklar, James; Molnar, William; Santella, Dennis; Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 13 Manhattan smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, October 07, 2013 1:25 PM

To: Gorman, John

Subject: RE: P.S. 13 Manhattan smoking ballast incident

John:

As a follow up to my previous email, 1 fixture containing 1 leaking pcb ballast was removed from room 429. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters were sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 24 hours in the room that is 4500 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 4500 cuft = 224 air changes.

Smoking ballast info:

Advance

No thermal protection

No manufacture date

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Thursday, October 03, 2013 2:50 PM To: 'Gorman, John' (Gorman, John@epa.gov)

Subject: P.S. 13 Manhattan smoking ballast incident

John,

P.S. 13 located at 1573 Madison Avenue in Manhattan had a visibly smoking ballast in the staff lounge rm 429 today 10/3. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will be completed today or tomorrow. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:55 AM

To:

Haklar, James; Molnar, William; Santella, Dennis; Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 153 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, October 07, 2013 1:32 PM

To: Gorman, John

Subject: RE: P.S. 153 Bronx smoking ballast incident

John:

As a follow up to my previous email, 6 fixtures containing 5 leaking pcb ballasts and 1 intact pcb ballast was removed from room 307. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters were sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 24 hours in the room that is 4000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm \times 1440 minutes / 4000 cuft = 252 air changes.

Smoking ballast info:

Advance

No thermal protection

No manufacture date

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Friday, October 04, 2013 8:41 AM
To: 'Gorman, John' (Gorman, John@epa.gov)
Subject: P.S. 153 Bronx smoking ballast incident

John,

P.S. 153 located at 650 Baychester Avenue in the Bronx had a visibly smoking ballast in room 307 this morning 10/4. The room was immediately secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will be completed today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards		
Phil		
Philip Napolitano		
Deputy Director of Facilities		
NYC Department of Education		-
Division of School Facilities		
44-36 Vernon Boulevard		
Long Island City, N.Y. 11101		
718 349 5583 tel		

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:55 AM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 157 Bronx external leak

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, October 08, 2013 11:59 AM

To: Gorman, John

Subject: P.S. 157 Bronx external leak

Good morning John:

P.S. 157 located at 757 Caldwell Avenue in the Bronx reported a burning odor from a light fixture in room 224 on Thursday 10/3. The room was immediately evacuated and secured. Our environmental contractor inspected the light fixtures in the room and found 6 leaking PCB ballasts. All ballasts and fixtures were removed Thursday evening. Prior to re-occupancy, the custodian noticed dried pieces of a tar like substance on the floor and a student's desk. Our environmental contractor re-inspected the room last night and confirmed that the tar may contain PCB's. The environmental contractor disposed of the impacted student desk as PCB contaminated waste and cleaned the impacted floor using Capsur. Our environmental consultant will take wipe samples of the impacted floor today. The room will remain closed until favorable wipe results are returned. Parental notification letters were sent.

Let me know if you have any questions.

Regards, Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:54 AM

To:

Haklar, James; Molnar, William; Santella, Dennis; Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 67 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Friday, October 04, 2013 2:38 PM

To: Gorman, John

Subject: RE: P.S. 67 Bronx smoking ballast incident

John:

As a follow up to my previous email, 6 fixtures containing 2 leaking pcb ballasts(smoker) and 4 non-pcb with historic stains was removed from room 507. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters were sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 24 hours in the room that is 8050 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 8050 cuft = 125 air changes.

Smoking ballast info:

Advance

No thermal protection

No manufacture date

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Thursday, October 03, 2013 10:27 AM
To: 'Gorman, John' (Gorman, John@epa.gov)
Subject: P.S. 67 Bronx smoking ballast incident

John:

P.S. 67 located at 2024 Mohegan Avenue in the Bronx had a visibly smoking ballast in classroom 507 today 10/3. The classroom was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:53 AM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 13 Manhattan smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, October 03, 2013 2:50 PM

To: Gorman, John

Subject: P.S. 13 Manhattan smoking ballast incident

John,

P.S. 13 located at 1573 Madison Avenue in Manhattan had a visibly smoking ballast in the staff lounge rm 429 today 10/3. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will be completed today or tomorrow. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano


Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101



From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:53 AM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 153 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Friday, October 04, 2013 8:41 AM

To: Gorman, John

Subject: P.S. 153 Bronx smoking ballast incident

John,

P.S. 153 located at 650 Baychester Avenue in the Bronx had a visibly smoking ballast in room 307 this morning 10/4. The room was immediately secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will be completed today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano


Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101



From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:52 AM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 67 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, October 03, 2013 10:27 AM

To: Gorman, John

Subject: P.S. 67 Bronx smoking ballast incident

John:

P.S. 67 located at 2024 Mohegan Avenue in the Bronx had a visibly smoking ballast in classroom 507 today 10/3. The classroom was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

교활병의 근무			

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:52 AM

To: Subject: Haklar, James; Molnar, William; Santella, Dennis; Schulz, Susan; Wienckoski, Ronald

FW: P.S. 49 Bronx smoking ballast and burning odor incidents

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, October 03, 2013 12:10 PM

To: Gorman, John

Subject: RE: P.S. 49 Bronx smoking ballast and burning odor incidents

John:

As a follow up to my previous email, 1 fixture containing 1 leaking pcb ballast was removed from room 106 (odor). 1 intact pcb ballast (smoker) and 2 non pcb ballast with historic staining was removed from room 204. Wipe samples were taken from room 204 and have been returned. Sample results are below the federal action level of 10 ug/cm². Both rooms will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) ran for over 15 hours in the hallway that is 3,168 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 900 minutes / 3,168 cuft = 198 air changes.

All ballast were Advance.

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Wednesday, October 02, 2013 3:53 PM **To:** 'Gorman, John' (Gorman, John@epa.gov)

Subject: P.S. 49 Bronx smoking ballast and burning odor incidents

John,

P.S. 049 located at 383 East 139th Street in the Bronx had a visibly smoking ballast in room #204 earlier today 6/25. There was also a report of a burning odor in room 106. Both rooms were immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit in room 204. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:52 AM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 49 Bronx smoking ballast and burning odor incidents

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, October 02, 2013 3:53 PM

To: Gorman, John

Subject: P.S. 49 Bronx smoking ballast and burning odor incidents

John,

P.S. 049 located at 383 East 139th Street in the Bronx had a visibly smoking ballast in room #204 earlier today 6/25. There was also a report of a burning odor in room 106. Both rooms were immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit in room 204. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano


Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101



From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:52 AM

To:

Haklar, James; Molnar, William; Santella, Dennis; Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 105 Queens smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, October 02, 2013 10:21 AM

To: Gorman, John

Subject: RE: P.S. 105 Queens smoking ballast incident

John:

As a follow up to my previous email, 3 fixtures containing 1 leaking pcb ballast(smoker) and 1 non-pcb with historic stains and 1 non pcb ballast were removed from room 312. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters were sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 16 hours in the room that is 5000 cuft. I used 700 cfm (in case the duct had a bend). $700 \text{ cfm} \times 960 \text{ minutes} / 5000 \text{ cuft} = 134 \text{ air changes}$.

Smoking ballast info:

Westinghouse

Thermally protected

No manufacture date

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, October 01, 2013 9:56 AM
To: 'Gorman, John' (Gorman, John@epa.gov)
Subject: P.S. 105 Queens smoking ballast incident

John,

P.S. 105 located at 420 Beach 51st Street in Queens had a visibly smoking ballast in classroom 312 this morning 10/1. The room was immediately secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

	zeBainz	
F	Phil	
	Philip Napolitano	
1	Deputy Director of Facilities	
1	NYC Department of Education	
	Division of School Facilities	
	44-36 Vernon Boulevard	
	Long Island City, N.Y. 11101	
	718 349 5583 tel	

From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:51 AM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 105 Queens smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.qov]

Sent: Tuesday, October 01, 2013 9:56 AM

To: Gorman, John

Subject: P.S. 105 Queens smoking ballast incident

John,

P.S. 105 located at 420 Beach 51st Street in Queens had a visibly smoking ballast in classroom 312 this morning 10/1. The room was immediately secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano


Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101



From:

Gorman, John

Sent:

Thursday, October 17, 2013 5:51 AM

To:

Haklar, James; Molnar, William; Santella, Dennis; Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 198 smoking ballast incident Thursday 9/26

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, October 01, 2013 9:31 AM

To: Gorman, John

Subject: RE: P.S. 198 smoking ballast incident Thursday 9/26

John:

As a follow up to my previous email, 1 fixture was removed from room the 1^{st} floor hallway. The fixture consisted of 1 leaking PCB ballast. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 16 hours in the hallway that is 14,400 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm \times 960 minutes / 14,400 cuft = 46 air changes.

Smoking ballast info:

Advance

No manufacture date

No thermal protection

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Monday, September 30, 2013 3:46 PM **To:** 'Gorman, John' (<u>Gorman.John@epa.gov</u>)

Subject: P.S. 198 smoking ballast incident Thursday 9/26

Good afternoon John:

We just received a report from P.S. 198 located at 1180 Tinton Avenue in the Bronx of a visibly smoking ballast in the 1st floor corridor on Thursday 9/26. The custodian failed to follow protocol and did not notify us until today. The corridor was evacuated and ventilated at the time of occurrence but was re-occupied soon after. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards,

Phil

From:

Gorman, John

Sent:

Monday, September 30, 2013 3:47 PM

To:

Evangelista, Pat; Haklar, James; Molnar, William; Newton, Caroline; Santella, Dennis;

Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 198 smoking ballast incident Thursday 9/26

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, September 30, 2013 3:46 PM


To: Gorman, John

Subject: P.S. 198 smoking ballast incident Thursday 9/26

Good afternoon John:

We just received a report from P.S. 198 located at 1180 Tinton Avenue in the Bronx of a visibly smoking ballast in the 1st floor corridor on Thursday 9/26. The custodian failed to follow protocol and did not notify us until today. The corridor was evacuated and ventilated at the time of occurrence but was re-occupied soon after. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Monday, September 30, 2013 11:26 AM

To:

Haklar, James; Molnar, William; Santella, Dennis; Schulz, Susan; Wienckoski, Ronald

Subject:

FW: P.S. 132 Bronx smoking ballast incident 9/26

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, September 30, 2013 11:20 AM

To: Gorman, John

Subject: RE: P.S. 132 Bronx smoking ballast incident 9/26

John:

As a follow up to my previous email, 3 fixtures containing 3 leaking pcb ballasts were removed from room B-17. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters were sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 24 hours in the room that is 6,000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 6,000 cuft = 168 air changes.

Smoking ballast info:

General Electric

Not thermally protected

No manufacture date

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Friday, September 27, 2013 9:33 AM **To:** 'Gorman, John' (Gorman, John@epa.gov)

Subject: P.S. 132 Bronx smoking ballast incident 9/26

John,

P.S. 132 located at 1245 Washington Avenue in the Bronx had a visibly smoking ballast in room #B17 last night 9/26. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe

samples will happen today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

	gai	

Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From: Gorman, John

Sent: Monday, September 30, 2013 9:14 AM

To: Haklar, James; Santella, Dennis; Schulz, Susan

Cc: Molnar, William; Wienckoski, Ronald

Subject: FW: PS 206 Brooklyn 2 smoking ballast incidents 9/26

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, September 30, 2013 9:10 AM

To: Gorman, John

Subject: RE: PS 206 Brooklyn 2 smoking ballast incidents 9/26

Good afternoon John:

As a follow up to my previous email, 3 fixtures were removed from room 301, they contained 3 leaking PCB ballasts. 5 fixtures were removed from room 414, they contained 5 leaking PCB ballasts. Wipe samples were taken from both rooms and have been returned. All sample results are below the federal action level of 10 ug/cm². Both rooms will be reoccupied. Parent notification letters will be sent. We ventilated each room with a pedestal fan and blower unit.

Blower (max rating 980 cfm) has been running for over 22 hours in classroom 301 which is 10,100 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1320 minutes / 10,100 cuft = 91 air changes.

Blower (max rating 980 cfm) has been running for over 21 hours in classroom 414 which is 14,600 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1260 minutes / 14,600 cuft = 60 air changes.

Smoking ballast info

Both Ballasts were Universal No thermal protection No manufacture date

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Friday, September 27, 2013 9:36 AM

To: 'Gorman, John'

Subject: PS 206 Brooklyn 2 smoking ballast incidents 9/26

John:

P.S. 206 located at Gravesend Neck Road Brooklyn had 2 visibly smoking ballasts in classrooms 301 and 414 yesterday 9/26. The rooms were immediately evacuated and secured. A fan was put in place to aid in ventilation. Our

environmental contractor will provide additional ventilation and inspect/remove the fixture today. Wipe samples will be taken as well. The rooms will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil

From: Gorman, John

Sent: Friday, September 27, 2013 3:27 PM

To: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline

Cc: Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 864 Brooklyn smoking ballast incident

Fourth reported ballast incident at P.S. 864 in Brooklyn.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Friday, September 27, 2013 8:24 AM

To: Gorman, John

Subject: RE: P.S. 864 Brooklyn smoking ballast incident

John:

As a follow up to my previous email, 1 row was inspected and removed from room 304. The row consisted of 3 fixtures and 3 ballasts, 1 leaking PCB ballast (smoking) and 2 NONPCB ballasts with historic staining. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 24 hours in the classroom that is 8500 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 8500 cuft = 118 air changes.

Smoking ballast info was not provided.

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Friday, September 20, 2013 8:29 AM **To:** 'Gorman, John' (Gorman, John@epa.gov)

Subject: P.S. 864 Brooklyn smoking ballast incident

John:

P.S. 864 located at 3109 Newkirk Avenue Brooklyn had a visibly smoking ballast in classroom 304 yesterday afternoon 9/19. The room was empty at the time of occurrence. The room has been secured and a fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. Wipe samples will be taken as well. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

From:

Gorman, John

Sent:

Friday, September 27, 2013 3:25 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 6 Bronx smoking ballast incident

Fourth reported ballast incident at P.S. 6 in the Bronx.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Friday, September 27, 2013 8:37 AM

To: Gorman, John

Subject: RE: P.S. 6 Bronx smoking ballast incident

John:

As a follow up to my previous email, 3 fixtures containing 2 leaking pcb ballasts and 1 intact pcb ballast were removed from room 214. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters were sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 12 hours in the room that is 9570 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 720 minutes / 9570 cuft = 52 air changes.

Smoking ballast info:

Universal

Not thermally protected

No manufacture date

Let me know if you have any questions

Regards,

Phil

From: Napolitano Philip

Sent: Tuesday, September 24, 2013 12:47 PM **To:** 'Gorman, John' (<u>Gorman, John@epa.gov</u>) **Subject:** P.S. 6 Bronx smoking ballast incident

Good afternoon John:

P.S. 006 located at 1000 East Tremont Avenue in the Bronx had a visibly smoking ballast in classroom #214 earlier today 9/24. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. The environmental contractor will provide additional ventilation with a blower unit. Fixture removal and wipe samples will happen today. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

	e			

Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Friday, September 27, 2013 3:23 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 132 Bronx smoking ballast incident 9/26

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Friday, September 27, 2013 9:33 AM

To: Gorman, John

Subject: P.S. 132 Bronx smoking ballast incident 9/26

John,

P.S. 132 located at 1245 Washington Avenue in the Bronx had a visibly smoking ballast in room #B17 last night 9/26. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano


Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101



From: Gorman, John

Sent: Friday, September 27, 2013 3:21 PM

To: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline

Cc: Molnar, William; Wienckoski, Ronald

Subject: FW: PS 206 Brooklyn 2 smoking ballast incidents 9/26

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Friday, September 27, 2013 9:36 AM


To: Gorman, John

Subject: PS 206 Brooklyn 2 smoking ballast incidents 9/26

John:

P.S. 206 located at Gravesend Neck Road Brooklyn had 2 visibly smoking ballasts in classrooms 301 and 414 yesterday 9/26. The rooms were immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will provide additional ventilation and inspect/remove the fixture today. Wipe samples will be taken as well. The rooms will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil



From:

Gorman, John

Sent:

Tuesday, September 24, 2013 12:53 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 6 Bronx smoking ballast incident

Third reported ballast issue at P.S. 006 in the Bronx.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 24, 2013 12:47 PM

To: Gorman, John

Subject: P.S. 6 Bronx smoking ballast incident

Good afternoon John:

P.S. 006 located at 1000 East Tremont Avenue in the Bronx had a visibly smoking ballast in classroom #214 earlier today 9/24. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. The environmental contractor will provide additional ventilation with a blower unit. Fixture removal and wipe samples will happen today. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Monday, September 23, 2013 12:05 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis

Subject:

FW: P.S. 70 Bronx leaking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, September 23, 2013 11:51 AM

To: Gorman, John

Subject: RE: P.S. 70 Bronx leaking ballast incident

John:

As a follow up to my previous email, 3 fixtures containing 2 leaking pcb ballasts, and 1 non pcb ballast with historic staining was removed from room 401. Our environmental contractor cleaned a one square foot area on the floor beneath the fixture. A total of 3 wipe samples were taken from the impacted floor after the cleaning. All wipe samples have been returned and results are below the detection limit thus below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 96 hours in the room that is 9,240 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 5760 minutes / 9,240 cuft = 436 air changes.

Leaking ballast info was not provided.

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Wednesday, September 18, 2013 1:57 PM To: 'Gorman, John' (Gorman.John@epa.gov)
Subject: P.S. 70 Bronx leaking ballast incident

Good afternoon John:

P.S. 70 located at 1691 Weeks Avenue in the Bronx had a smoking/leaking ballast in room 401 yesterday afternoon 9/17. The room was immediately evacuated and secured. The leak was reported on the classroom's floor. A fan was put in place to aid in ventilation. Our environmental contractor will begin the cleaning process tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken from the impacted area once cleaning is complete. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

From:

Gorman, John

Sent:

Friday, September 20, 2013 8:12 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

Fw: P.S. 49 Bronx smoking ballast incident

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Friday, September 20, 2013 12:00:11 PM

To: Gorman, John

Subject: RE: P.S. 49 Bronx smoking ballast incident

John:

As a follow up to my previous email, 1 row was inspected and removed from room 342. The row consisted of 3 leaking PCB ballasts. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for 16 hours in the classroom that is 2,880 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 960 minutes / 2,880 cuft = 233 air changes.

Smoking ballast info:

Universal manufacturing

No thermal protection

No manufacture date

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Thursday, September 19, 2013 11:17 AM

To: 'Gorman, John'

Subject: P.S. 49 Bronx smoking ballast incident

John,

P.S. 049 located at 383 East 139th Street in the Bronx had a visibly smoking ballast in room #342 earlier today 9/19. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil

Philip Napolitano Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Friday, September 20, 2013 8:10 PM

To: Subject:

Fw: Remote ballast panel information

Attachments:

Copy of Remote ballast panels EPA 9-20-13.xlsx

Haklar, James; Schulz, Susan; Santella, Dennis; Newton, Caroline

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Friday, September 20, 2013 1:04:39 PM

To: Gorman, John

Subject: RE: Remote ballast panel information

John,

Two ballast panels were reported in K084 this morning. I added K084 to the attached spreadsheet. Our environmental contractor will inspect on Monday and we will prioritize removals based on the findings. I will keep you posted.


From: Napolitano Philip

Sent: Monday, August 26, 2013 12:10 PM To: 'Gorman, John' (Gorman.John@epa.gov) Subject: Remote ballast panel information

Good afternoon John,

Attached is a list of schools that, based on current information, have remote ballast panels or individual remote ballast boxes. There appears to be two different configurations. Ten schools have remote ballast panels that are in the hallway which control the classroom lighting. Six schools have remote ballasts for the gym or the auditorium. Other than custodian engineer visual inspections, we currently do not have a plan to internally inspect the cabinets or ballast boxes in these schools. As in the past, our custodians and skilled trades personnel will continue to report specific ballast failures or instances that may warrant an inspection from our environmental contractor. Moving forward, I will update you if there are changes to the attached list.

Regards, Phil



	Remote	Ballast Panels			
Borough	Bldg. ID	Comments			
Bk North	16K081	4 Panels; 2 on each floor, 3rd & 4th Fl. Hallways. (T12 building upgrade to begin in Fall 2013)			
Bk North	19K328	6 Panels (All ballasts were removed by SCA Summer 2013)			
Bk South	21K303	1 ballast panel located in room 144. School was converted to T8's in 2011.			
Bk South 21K370		1 panel located in 2nd floor hallway for audioturium light fixtures.			
Bronx	11X160	Rm. 224 & 330 2 panels.			
Bronx	11X455	1 Panel.			
Bronx	09X126	4 panels; 2 on each floor. 1st and 2nd floors			
Bronx	12X047	2 Panels located in Auditorium			
Manhattan	05M030	6 panels; 2 on each floor. 2nd, 3rd and 4th floors			
Queens	26Q430	1 panel located in gymnasium			
Queens	25Q025	Room B28, 1 Panel			
Queens	30Q017	3 Racks located in gymnasium			
Queens	28Q174	1 Panel located in gymnasium			
Staten Island	31R032	4 panels; 2 on each floor. 2nd and 3rd floors			
Bk North	15K834	Remote ballasts located on stage power gymnsaium lights T12 building (SCA upgrade in progress)			

Bk North	23K332	4 panels located in the hallways. T12 ballasts have been removed this summer by SCA		
Bk North	14K084	2 panels. 1 located in 249 bathroom. 1 located in 255 bathroom.		

From: Gorman, John

Sent: Friday, September 20, 2013 9:01 AM

To: Haklar, James; Schulz, Susan; Newton, Caroline; Santella, Dennis; Evangelista, Pat;

Molnar, William; Wienckoski, Ronald

Subject: Fw: P.S. 864 Brooklyn smoking ballast incident

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Friday, September 20, 2013 8:29:26 AM


To: Gorman, John

Subject: P.S. 864 Brooklyn smoking ballast incident

John:

P.S. 864 located at 3109 Newkirk Avenue Brooklyn had a visibly smoking ballast in classroom 304 yesterday afternoon 9/19. The room was empty at the time of occurrence. The room has been secured and a fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. Wipe samples will be taken as well. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil



From:

Gorman, John

Sent:

Thursday, September 19, 2013 11:20 AM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 49 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, September 19, 2013 11:17 AM

To: Gorman, John

Subject: P.S. 49 Bronx smoking ballast incident

John,

P.S. 049 located at 383 East 139th Street in the Bronx had a visibly smoking ballast in room #342 earlier today 9/19. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

From:

Gorman, John

Sent:

Thursday, September 19, 2013 11:17 AM Haklar, James; Schulz, Susan; Santella, Dennis

To: Subject:

FW: P.S. 23 Staten Island smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, September 19, 2013 11:11 AM

To: Gorman, John

Subject: RE: P.S. 23 Staten Island smoking ballast incident

John:

As a follow up to my previous email, 3 fixtures were inspected and found to contain 3 leaking pcb ballasts from room 303. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The classroom will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and a blower unit.

The blower (max rating 980 cfm) has been running for over 24 hours in the classroom that is 6,500 cuft. I used 700 cfm (in case the ducts had a bend). 700 cfm x 1440 minutes / 6,500 cuft = 155 air changes.

Smoking ballast info:

Universal

No manufacture date

No Thermal protection

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, September 17, 2013 2:14 PM **To:** 'Gorman, John' (Gorman, John@epa.gov)

Subject: P.S. 23 Staten Island smoking ballast incident

Good afternoon John,

P.S. 023 located at 30 Natick Street in Staten Island had a visibly smoking ballast in classroom 303 this afternoon 9/17. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tomorrow. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

From: Gorman, John

Sent: Wednesday, September 18, 2013 2:31 PM

To: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 70 Bronx leaking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, September 18, 2013 1:57 PM


To: Gorman, John

Subject: P.S. 70 Bronx leaking ballast incident

Good afternoon John:

P.S. 70 located at 1691 Weeks Avenue in the Bronx had a smoking/leaking ballast in room 401 yesterday afternoon 9/17. The room was immediately evacuated and secured. The leak was reported on the classroom's floor. A fan was put in place to aid in ventilation. Our environmental contractor will begin the cleaning process tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken from the impacted area once cleaning is complete. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Tuesday, September 17, 2013 2:30 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 23 Staten Island smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 17, 2013 2:14 PM

To: Gorman, John

Subject: P.S. 23 Staten Island smoking ballast incident

Good afternoon John,

P.S. 023 located at 30 Natick Street in Staten Island had a visibly smoking ballast in classroom 303 this afternoon 9/17. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tomorrow. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

From:

Gorman, John

Sent:

Tuesday, September 17, 2013 11:11 AM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 42 Staten Island smoking T8 ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 17, 2013 11:03 AM

To: Gorman, John

Subject: P.S. 42 Staten Island smoking T8 ballast incident

John:

P.S. 42 located at 380 Genesee Avenue in Staten Island had a visibly smoking T8 ballast in room 309 yesterday 9/16. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. The environmental contractor inspected the fixture last night and found an intact NON PCB ballast with no leaks or stains. We did not take wipe samples. Parent notification letters will be sent.

Regards,

Phil

Philip Napolitano


Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101



From:

Gorman, John

Sent:

Tuesday, September 17, 2013 8:50 AM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 185 Queens smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 17, 2013 8:40 AM

To: Gorman, John

Subject: RE: P.S. 185 Queens smoking ballast incident

John:

As a follow up to my previous email, 3 fixtures were inspected and found to contain 3 intact pcb ballasts with no stains or leaks observed from room 305. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The classroom will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and a blower unit.

The blower (max rating 980 cfm) has been running for over 48 hours in the classroom that is 8,500 cuft. I used 700 cfm (in case the ducts had a bend). 700 cfm x 2880 minutes / 8,500 cuft = 237 air changes.

Smoking ballast info:

Advance

No manufacture date

Thermally protected

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Thursday, September 12, 2013 2:26 PM

To: 'Gorman, John'

Subject: P.S. 185 Queens smoking ballast incident

John:

P.S. 185 located at 147-26 25 Drive in Queens had a visibly smoking ballast in room 305 today 9/12. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. The environmental contractor will provide additional ventilation with a blower unit. Fixture removal and wipe samples will happen tonight. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil

From: Gorman, John

Sent: Friday, September 13, 2013 10:48 AM

To: Haklar, James; Schulz, Susan; Santella, Dennis; Molnar, William; Wienckoski, Ronald

Subject: Fw: P.S. 161 Bronx smoking ballast incident

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Friday, September 13, 2013 10:41:45 AM

To: Gorman, John

Subject: RE: P.S. 161 Bronx smoking ballast incident

John:

As a follow up to my previous email, 1 fixture containing 1 leaking pcb ballast was removed from the cafeteria. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The cafeteria will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and two blower units.

The blowers (max rating 980 cfm) have been running for over 17 hours in the cafeteria that is 30,000 cuft. I used 1400 cfm (for the 2 blowers) (in case the ducts had a bend). $1400 \text{ cfm} \times 1020 \text{ minutes} / 30,000 \text{ cuft} = 47 \text{ air changes}$.

Smoking ballast info:

Universal

No manufacture date

No thermal protection

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Thursday, September 12, 2013 2:21 PM **To:** "Gorman, John' (Gorman.John@epa.gov)' **Subject:** P.S. 161 Bronx smoking ballast incident

John:

P.S. 161 located at 628 Tinton Avenue in the Bronx had a visibly smoking ballast in the cafeteria earlier today 9/12. The cafeteria was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

From:

Gorman, John

Sent:

Thursday, September 12, 2013 2:29 PM

To:

Haklar, James; Santella, Dennis; Newton, Caroline; Schulz, Susan; LaPosta, Dore;

Evangelista, Pat; Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 185 Queens smoking ballast incident

This is the fourth reported ballast failure at P.S. 185 in Queens.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, September 12, 2013 2:26 PM


To: Gorman, John

Subject: P.S. 185 Queens smoking ballast incident

John:

P.S. 185 located at 147-26 25 Drive in Queens had a visibly smoking ballast in room 305 today 9/12. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. The environmental contractor will provide additional ventilation with a blower unit. Fixture removal and wipe samples will happen tonight. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil



From: Gorman, John

Sent: Thursday, September 12, 2013 2:26 PM

To: Haklar, James; Schulz, Susan; Newton, Caroline; Santella, Dennis; Evangelista, Pat;

Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 161 Bronx smoking ballast incident

Second ballast incident this month for P.S. 161 in the Bronx.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, September 12, 2013 2:21 PM


To: Gorman, John

Subject: P.S. 161 Bronx smoking ballast incident

John:

P.S. 161 located at 628 Tinton Avenue in the Bronx had a visibly smoking ballast in the cafeteria earlier today 9/12. The cafeteria was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Thursday, September 12, 2013 2:08 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 278 Brooklyn smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, September 12, 2013 2:05 PM

To: Gorman, John

Subject: RE: P.S. 278 Brooklyn smoking ballast incident

John:

As a follow up to my previous email, 2 fixtures were inspected and found to contain 1 intact PCB ballast (smoke) and 1 non pcb ballast from room 209. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 24 hours in the room that is 9,600 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 9,600 cuft = 105 air changes.

Smoking ballast info:

Universal

No manufacture date

No thermal protection

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, September 10, 2013 1:22 PM

To: 'Gorman, John'

Subject: P.S. 278 Brooklyn smoking ballast incident

John:

P.S. 278 located at 1925 Stuart Street in Brooklyn had a visibly smoking ballast in room 209 earlier today 9/10. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tomorrow. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

From:

Gorman, John

Sent:

Thursday, September 12, 2013 2:02 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 185 Queens smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, September 12, 2013 1:58 PM

To: Gorman, John

Subject: RE: P.S. 185 Queens smoking ballast incident

John:

As a follow up to my previous email, 5 fixtures were inspected and found to contain 2 leaking PCB ballasts(1 smoked) and 3 intact PCB ballast from room 203. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 24 hours in the room that is 10,800 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 10,800 cuft = 93 air changes.

Smoking ballast info was not provided

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, September 10, 2013 9:12 AM

To: 'Gorman, John'

Subject: P.S. 185 Queens smoking ballast incident

John:

P.S. 185 located at 147-26 25 Drive in Queens had a visibly smoking ballast in room 203 today 9/10. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. The environmental contractor will provide additional ventilation with a blower unit. Fixture removal and wipe samples will happen tonight. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil

Philip Napolitano
Deputy Director of Facilities
NYC Department of Education
Division of School Facilities

44-36 Vernon Boulevard Long Island City, N.Y. 11101 718 349 5583 tel

From: Gorman, John

Sent: Wednesday, September 11, 2013 11:33 AM

To: Haklar, James; Schulz, Susan; Santella, Dennis; Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 19 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, September 11, 2013 11:32 AM

To: Gorman, John

Subject: RE: P.S. 19 Bronx smoking ballast incident

John:

As a follow up to my previous email, 1 fixture was inspected and found to contain 1 leaking PCB ballast from Staircase #7. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The staircase will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 12 hours in the staircase that is 3,000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 720 minutes / 3,000 cuft = 168 air changes.

Smoking ballast info was not provided. The label was burnt off.

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, September 10, 2013 3:26 PM
To: 'Gorman, John' (Gorman, John@epa.gov)
Subject: P.S. 19 Bronx smoking ballast incident

John:

P.S. 19 located at 4318 Katonah Avenue in the Bronx had a visibly smoking ballast in staircase #7 this afternoon 9/10. The staircase doors were immediately closed with caution tape (we did not lock the doors). A fan was put in place to aid in ventilation and the exit doors are open. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. The staircase will remain closed pending wipe sample results. The school administration was directed that in the event of a building emergency the staircase can be used. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards,

Phil

From:

Gorman, John

Sent:

Wednesday, September 11, 2013 11:26 AM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 116 Queens smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, September 11, 2013 11:16 AM

To: Gorman, John

Subject: RE: P.S. 116 Queens smoking ballast incident

John:

As a follow up to my previous email, 1 fixture was inspected and found to contain 1 leaking PCB ballast from the boiler room. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The boiler room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 41 hours in the room that is 67,000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 2460 minutes / 67,000 cuft = 25 air changes.

Smoking ballast info was not provided

Let me know if you have any questions

Regards,

Phil

From: Napolitano Philip

Sent: Monday, September 09, 2013 4:21 PM
To: 'Gorman, John' (Gorman, John@epa.gov)
Subject: P.S. 116 Queens smoking ballast incident

Good afternoon John:

P.S. 116 in Queens had a visibly smoking ballast in the boiler room this afternoon 9/9. The boiler room was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tomorrow. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education Division of School Facilities 44-36 Vernon Boulevard Long Island City, N.Y. 11101 718 349 5583 tel

From:

Gorman, John

Sent:

Tuesday, September 10, 2013 3:43 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 161 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 10, 2013 3:36 PM

To: Gorman, John

Subject: RE: P.S. 161 Bronx smoking ballast incident

John:

As a follow up to my previous email, one fixture was inspected and found to contain 1 intact NONPCB ballast with no staining. Wipe samples were not taken. The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit to remove any lingering odor.

Smoking ballast was NONPCB

Let me know if you have any questions

Regards, Phil


From: Napolitano Philip

Sent: Tuesday, September 10, 2013 8:52 AM **To:** 'Gorman, John' (<u>Gorman, John@epa.gov</u>) **Subject:** P.S. 161 Bronx smoking ballast incident

Good morning John:

P.S. 161 located at 628 Tinton Avenue in the Bronx had a visibly smoking ballast in the general office room 118 this morning 9/10. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Tuesday, September 10, 2013 3:29 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 19 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 10, 2013 3:26 PM


To: Gorman, John

Subject: P.S. 19 Bronx smoking ballast incident

John:

P.S. 19 located at 4318 Katonah Avenue in the Bronx had a visibly smoking ballast in staircase #7 this afternoon 9/10. The staircase doors were immediately closed with caution tape (we did not lock the doors). A fan was put in place to aid in ventilation and the exit doors are open. Fixture removal and wipe samples will happen tonight. The environmental contractor will provide additional ventilation with a blower unit. The staircase will remain closed pending wipe sample results. The school administration was directed that in the event of a building emergency the staircase can be used. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Tuesday, September 10, 2013 1:58 PM

To:

Haklar, James; Schulz, Susan; Newton, Caroline; Santella, Dennis; Evangelista, Pat;

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 278 Brooklyn smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 10, 2013 1:22 PM


To: Gorman, John

Subject: P.S. 278 Brooklyn smoking ballast incident

John:

P.S. 278 located at 1925 Stuart Street in Brooklyn had a visibly smoking ballast in room 209 earlier today 9/10. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tomorrow. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Tuesday, September 10, 2013 9:14 AM

To:

LaPosta, Dore

Cc:

Haklar, James; Schulz, Susan; Newton, Caroline; Santella, Dennis; Evangelista, Pat;

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 185 Queens smoking ballast incident

Third reported ballast incident at P.S. 185 in Queens.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 10, 2013 9:12 AM


To: Gorman, John

Subject: P.S. 185 Queens smoking ballast incident

John:

P.S. 185 located at 147-26 25 Drive in Queens had a visibly smoking ballast in room 203 today 9/10. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. The environmental contractor will provide additional ventilation with a blower unit. Fixture removal and wipe samples will happen tonight. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned

Regards Phil



From: Gorman, John

Sent: Tuesday, September 10, 2013 8:54 AM

To: LaPosta, Dore

Cc: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 161 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 10, 2013 8:52 AM


To: Gorman, John

Subject: P.S. 161 Bronx smoking ballast incident

Good morning John:

P.S. 161 located at 628 Tinton Avenue in the Bronx had a visibly smoking ballast in the general office room 118 this morning 9/10. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From: Gorman, John

Sent: Monday, September 09, 2013 4:36 PM

To: LaPosta, Dore

Cc: Haklar, James; Schulz, Susan; Newton, Caroline; Santella, Dennis; Evangelista, Pat;

Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 116 Queens smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, September 09, 2013 4:21 PM


To: Gorman, John

Subject: P.S. 116 Queens smoking ballast incident

Good afternoon John:

P.S. 116 in Queens had a visibly smoking ballast in the boiler room this afternoon 9/9. The boiler room was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tomorrow. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Thursday, September 05, 2013 2:17 PM

To:

Schulz, Susan; Haklar, James; Santella, Dennis

Subject:

Fw: P.S. 42 Bronx two smoking ballasts incidents

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Thursday, September 05, 2013 1:35:31 PM

To: Gorman, John

Subject: RE: P.S. 42 Bronx two smoking ballasts incidents

John:

As a follow up to my previous email, 3 fixtures were inspected and found to contain 1 leaking PCB ballast (smoke), 1 intact non pcb ballast, and 1 intact pcb ballast from room 102. 1 fixture was inspected in room 109 and found to contain 1 intact non pcb ballast. Wipe samples were taken from both rooms and have been returned. Sample results are below the federal action level of 10 ug/cm². The rooms will be re-occupied. Parent notification letters will be sent. We ventilated room 102 with a pedestal fan and blower unit.

The blower (max rating 980 cfm) ran for 18 hours in the room that is 10,200 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1080 minutes / 10,200 cuft = 74 air changes.

Room 102 smoking ballast info:

General Electric

No manufacture date

Thermally protected

Room 109 smoking ballast was NONPCB

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, September 03, 2013 3:28 PM **To:** "Gorman, John' (Gorman.John@epa.gov)'

Subject: P.S. 42 Bronx two smoking ballasts incidents

John,

P.S. 42 located at 1537 Washington Avenue in the Bronx had two visibly smoking ballasts earlier today 9/3 in room's 102 and 109. The rooms were immediately evacuated and secured. Fans were put in place to aid in ventilation. Fixture removal and wipe samples will be completed tomorrow. The environmental contractor will provide additional

ventilation with a blower unit in each room. The rooms will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned. Regards

Philip Napolitano Deputy Director of Facilities

Phil

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

718 349 5583 tel

From: Gorman, John

Sent: Wednesday, September 04, 2013 3:49 PM **To:** Haklar, James; Schulz, Susan; Santella, Dennis

Cc: Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 41 Manhattan smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, September 04, 2013 3:48 PM

To: Gorman, John

Subject: RE: P.S. 41 Manhattan smoking ballast incident

John:

As a follow up to my previous email, 1 fixture was inspected and found to contain 1 intact PCB ballast from room 328. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 15 hours in the room that is 10,000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 900 minutes / 10,000 cuft = 63 air changes.

Smoking ballast info:

Sola Dynatron

No manufacture date

Thermally protected

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, September 03, 2013 3:33 PM **To:** 'Gorman, John' (Gorman, John@epa.gov)

Subject: P.S. 41 Manhattan smoking ballast incident

John:

P.S. 41 located at 116 West 11th Street Manhattan had a visibly smoking ballast in the art room 328 earlier today 9/3. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect and remove the fixture tomorrow. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil

From:

Gorman, John

Sent:

Wednesday, September 04, 2013 3:49 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 105 Queens smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, September 04, 2013 3:44 PM

To: Gorman, John

Subject: RE: P.S. 105 Queens smoking ballast incident

John:

As a follow up to my previous email, 1 fixture was inspected and found to contain 1 intact PCB ballast from room 201. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 20 hours in the room that is 7500 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1200 minutes / 7500 cuft = 112 air changes.

Smoking ballast info:

Advance

No manufacture date

Thermal protection unknown

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, September 03, 2013 9:09 AM
To: 'Gorman, John' (Gorman, John@epa.gov)
Subject: P.S. 105 Queens smoking ballast incident

Good morning John,

P.S. 105 located at 420 Beach 51st Street in Queens had a visibly smoking ballast in the teacher's resource room 201 earlier today 9/3. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards		
Phil		
Philip Napolitano		
Deputy Director of Facilities		
NYC Department of Education		
Division of School Facilities		
44-36 Vernon Boulevard		
Long Island City, N.Y. 11101		
718 349 5583 tel		

From:

Gorman, John

Sent: To: Wednesday, September 04, 2013 3:34 PM Haklar, James; Schulz, Susan; Santella, Dennis

Subject:

FW: P.S. 184 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, September 04, 2013 3:12 PM

To: Gorman, John

Subject: RE: P.S. 184 Bronx smoking ballast incident

John:

As a follow up to my previous email, 1 fixture was inspected and found to contain 1 intact PCB ballast from room 428. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 19 hours in the room that is 3,500 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1140 minutes / 3,500 cuft = 228 air changes.

Smoking ballast info:

Universal

No manufacture date

No thermal protection

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, September 03, 2013 11:49 AM
To: 'Gorman, John' (Gorman, John@epa.gov)
Subject: P.S. 184 Bronx smoking ballast incident

John:

P.S. 184 located at 778 Forest Avenue in the Bronx had a visibly smoking ballast in the general office room 428 earlier today 9/3. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards,

Phil

From: Gorman, John

Sent: Tuesday, September 03, 2013 3:36 PM

To: LaPosta, Dore

Cc: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 41 Manhattan smoking ballast incident

Fourth report of smoking ballasts at P.S. 41 in Manhattan since April.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 03, 2013 3:33 PM


To: Gorman, John

Subject: P.S. 41 Manhattan smoking ballast incident

John:

P.S. 41 located at 116 West 11th Street Manhattan had a visibly smoking ballast in the art room 328 earlier today 9/3. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect and remove the fixture tomorrow. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil



From: Gorman, John

Sent: Tuesday, September 03, 2013 3:32 PM

To: LaPosta, Dore

Cc: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 42 Bronx two smoking ballasts incidents

Third report of smoking ballasts at P.S. 42 in the Bronx since mid-July.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 03, 2013 3:28 PM

To: Gorman, John

Subject: P.S. 42 Bronx two smoking ballasts incidents

John,

P.S. 42 located at 1537 Washington Avenue in the Bronx had two visibly smoking ballasts earlier today 9/3 in room's 102 and 109. The rooms were immediately evacuated and secured. Fans were put in place to aid in ventilation. Fixture removal and wipe samples will be completed tomorrow. The environmental contractor will provide additional ventilation with a blower unit in each room. The rooms will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano

Deputy Director of Facilities


NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

718 349 5583 tel



From: Gorman, John

Sent: Tuesday, September 03, 2013 11:50 AM

To: LaPosta, Dore

Cc: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 184 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 03, 2013 11:49 AM


To: Gorman, John

Subject: P.S. 184 Bronx smoking ballast incident

John:

P.S. 184 located at 778 Forest Avenue in the Bronx had a visibly smoking ballast in the general office room 428 earlier today 9/3. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From: Gorman, John

Sent: Tuesday, September 03, 2013 9:22 AM

To: LaPosta, Dore

Cc: Schulz, Susan; Haklar, James; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: FW: P.S. 105 Queens smoking ballast incident

Second reported ballast failure for PS. 105 in Queens.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, September 03, 2013 9:09 AM

To: Gorman, John

Subject: P.S. 105 Queens smoking ballast incident

Good morning John,

P.S. 105 located at 420 Beach 51st Street in Queens had a visibly smoking ballast in the teacher's resource room 201 earlier today 9/3. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano

Deputy Director of Facilities


NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

718 349 5583 tel



From:

Gorman, John

Sent:

Friday, August 30, 2013 3:07 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

FW: Harry Vanarsdale HS (K650) smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Friday, August 30, 2013 2:55 PM

To: Gorman, John

Subject: RE: Harry Vanarsdale HS (K650) smoking ballast incident

John:

As a follow up to my previous email, 4 fixtures were inspected and found to contain 4 leaking pcb ballasts from room 130. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 25 hours in the room that is 8,000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1500 minutes / 8,000 cuft = 131 air changes.

Smoking ballast info:

Westinghouse

No manufacture date

Thermally protection unknown

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Thursday, August 29, 2013 1:54 PM **To:** 'Gorman, John' (<u>Gorman.John@epa.gov</u>)

Subject: Harry Vanarsdale HS (K650) smoking ballast incident

Good afternoon John:

Harry Vanarsdale H.S.(K650) located at 257 N 6th Street in Brooklyn had a visibly smoking ballast in classroom 103 last night 8/28. The room was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

From: Gorman, John

Sent: Friday, August 30, 2013 11:43 AM

To: LaPosta, Dore

Cc: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: Fw: Harry Vanarsdale HS (K650) smoking ballast incident

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Thursday, August 29, 2013 1:53:50 PM


To: Gorman, John

Subject: Harry Vanarsdale HS (K650) smoking ballast incident

Good afternoon John:

Harry Vanarsdale H.S.(K650) located at 257 N 6th Street in Brooklyn had a visibly smoking ballast in classroom 103 last night 8/28. The room was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Wednesday, August 28, 2013 11:15 AM

To:

Haklar, James; Schulz, Susan; Santella, Dennis

Subject:

Fw: P.S. 142 Bronx smoking ballast incident

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Wednesday, August 28, 2013 10:48:25 AM

To: Gorman, John

Subject: RE: P.S. 142 Bronx smoking ballast incident

John:

As a follow up to my previous email, 1 fixture was inspected and found to contain 1 intact pcb ballast from room B21. The only the ballast was removed. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for over 36 hours in the room that is 11,623 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 2160 minutes / 11,623 cuft = 130 air changes.

Smoking ballast info:

Advance

No manufacture date

Thermally protected

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Tuesday, August 27, 2013 12:08 PM

To: 'Gorman, John'

Subject: P.S. 142 Bronx smoking ballast incident

Good afternoon John,

P.S. 142 located at 3750 Baychester Avenue in the Bronx had a visibly smoking ballast in room #B21 yesterday 8/26. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil

Philip Napolitano Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

718 349 5583 tel

From: Gorman, John

Sent: Tuesday, August 27, 2013 12:16 PM

To: LaPosta, Dore

Cc: Newton, Caroline; Schulz, Susan; Haklar, James; Santella, Dennis; Evangelista, Pat;

Molnar, William; Wienckoski, Ronald

Subject: Fw: P.S. 142 Bronx smoking ballast incident

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Tuesday, August 27, 2013 12:08:04 PM

To: Gorman, John

Subject: P.S. 142 Bronx smoking ballast incident

Good afternoon John,

P.S. 142 located at 3750 Baychester Avenue in the Bronx had a visibly smoking ballast in room #B21 yesterday 8/26. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen today. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil

Philip Napolitano
Deputy Director of Facilities


NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

718 349 5583 tel



From:

Gorman, John

Sent:

Monday, August 26, 2013 3:55 PM

To: Cc:

LaPosta, Dore

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: Attachments:

FW: Remote ballast panel information Remote ballast panels 8-26-13.xlsx

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, August 26, 2013 12:10 PM


To: Gorman, John

Subject: Remote ballast panel information

Good afternoon John,

Attached is a list of schools that, based on current information, have remote ballast panels or individual remote ballast boxes. There appears to be two different configurations. Ten schools have remote ballast panels that are in the hallway which control the classroom lighting. Six schools have remote ballasts for the gym or the auditorium. Other than custodian engineer visual inspections, we currently do not have a plan to internally inspect the cabinets or ballast boxes in these schools. As in the past, our custodians and skilled trades personnel will continue to report specific ballast failures or instances that may warrant an inspection from our environmental contractor. Moving forward, I will update you if there are changes to the attached list.

Regards, Phil



Remote Ballast Panels						
Borough	Bldg. ID	Comments				
Bk North	16K081	4 Panels; 2 on each floor, 3rd & 4th Fl. Hallways. (T12 building upgrade to begin in Fall 2013)				
Bk North	19K328	6 Panels (All ballasts were removed by SCA Summer 2013)				
Bk South	21K303	1 ballast panel located in room 144. School was converted to T8's in 2011.				
Bk South	21K370	1 panel located in 2nd floor hallway for audioturium light fixtures.				
Bronx	11X160	Rm. 224 & 330 2 panels.				
Bronx	11X455	1 Panel.				
Bronx	09X126	4 panels; 2 on each floor. 1st and 2nd floors				
Bronx	12X047	2 Panels located in Auditorium				
Manhattan	05M030	6 panels; 2 on each floor. 2nd, 3rd and 4th floors				
Queens	26Q430	1 panel located in gymnasium				
Queens	25Q025	Room B28, 1 Panel				
Queens	30Q017	3 Racks located in gymnasium				
Queens	28Q174	1 Panel located in gymnasium				
Staten Island	31R032	4 panels; 2 on each floor. 2nd and 3rd floors				
Bk North	15K834	Remote ballasts located on stage power gymnsaium lights T12 building (SCA upgrade in progress)				

	4 panels	located in the hallways. T12
1	ballasts l	nave been removed this
Bk North 23	K332 summer	by SCA

From:

Gorman, John

Sent:

Friday, August 23, 2013 1:22 PM

To:

Haklar, James; Schulz, Susan; Santella, Dennis

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

Fw: P.S. 175 Manhattan smoking ballast incident

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Friday, August 23, 2013 1:04:36 PM

To: Gorman, John

Subject: RE: P.S. 175 Manhattan smoking ballast incident

Good afternoon John:

As a follow up to my previous email, 1 fixture was inspected in room 321. The fixture contained 1 intact pcb ballast with historic staining. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) has been running for 19 hours in the classroom that is 4500 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1140 minutes / 4500 cuft = 177 air changes.

Smoking ballast info was not provided

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Wednesday, August 21, 2013 4:16 PM **To:** 'Gorman, John' (Gorman.John@epa.gov)

Subject: P.S. 175 Manhattan smoking ballast incident

Good afternoon John,

P.S. 175 located at 175 West 134th Street in Manhattan had a visibly smoking ballast in classroom 321 this afternoon 8/21. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tomorrow. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards Phil Philip Napolitano Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

718 349 5583 tel

From: Gorman, John

Sent: Wednesday, August 21, 2013 4:20 PM

To: LaPosta, Dore

Cc: Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject: Fw: P.S. 175 Manhattan smoking ballast incident

Second reported failure at P.S. 175 in Manhattan since June.

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Wednesday, August 21, 2013 4:16:17 PM

To: Gorman, John

Subject: P.S. 175 Manhattan smoking ballast incident

Good afternoon John,

P.S. 175 located at 175 West 134th Street in Manhattan had a visibly smoking ballast in classroom 321 this afternoon 8/21. The room was immediately evacuated and secured. A fan was put in place to aid in ventilation. Fixture removal and wipe samples will happen tomorrow. The environmental contractor will provide additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano
Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

718 349 5583 tel

From:

Gorman, John

Sent:

Wednesday, August 21, 2013 11:16 AM

To:

Haklar, James; Santella, Dennis; Schulz, Susan

Subject:

FW: P.S. 825 Staten Island leaking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, August 21, 2013 11:10 AM

To: Gorman, John

Subject: RE: P.S. 825 Staten Island leaking ballast incident

John:

As a follow up to my previous email, 1 fixture containing 1 leaking pcb ballast was removed from rm 119. Our environmental contractor cleaned the impacted floor. 5 Wipe samples were taken from the floor and have been returned. All sample results are below the detection limit thus below the federal action level of 10 ug/cm². The classroom will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit through the house exhaust shaft.

The blower (max rating 980 cfm) ran for over 24 hours in the classroom that is 8,000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 3000 cuft = 336 air changes.

Smoking ballast info:

Universal

No manufacture date

No thermal protection

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Monday, August 05, 2013 10:22 AM

To: 'Gorman, John'

Subject: P.S. 825 Staten Island leaking ballast incident

John:

P.S. 825 located at 6581 Hylan Boulevard in Staten Island had a leaking ballast this morning 8/5 in classroom 119. The room was unoccupied at the time it was discovered, it was immediately secured. It appears there is a drop on the floor below the fixture. A fan was put in place to aid in ventilation. The windows in the room are fixed closed. The room has an exhaust system that vents out through the roof. The fixture will be removed and our environmental contractor will clean any impacted tiles, once it is completed wipe samples will be taken. The environmental contractor will also provide

additional ventilation with a blower unit. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards,

Phil

From: Gorman, John

Sent: Wednesday, August 21, 2013 11:14 AM **To:** Haklar, James; Schulz, Susan; Santella, Dennis

Subject: FW: P.S. 150 Bronx smoking ballast incident


From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, August 21, 2013 10:32 AM

To: Gorman, John

Subject: RE: P.S. 150 Bronx smoking ballast incident

The occupant in the office reported a burning odor(from an unknown source). Due to the hypersensitivity at the school surrounding smoking light fixtures, it was assumed it was from a ballast. The contractor arrived on site a few hours later, and found all lights to be working with no smoke or odor present. Upon questioning, school staff confirmed the light fixtures did not smoke.



From:

Gorman, John

Sent:

Wednesday, August 21, 2013 11:13 AM

To:

Haklar, James; Schulz, Susan; Santella, Dennis

Subject:

FW: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.


From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Wednesday, August 21, 2013 10:53 AM

To: Gorman, John

Subject: RE: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

I will have a list of schools for you by next week. Preliminary numbers look to be around 15 buildings.



From:

Gorman, John

Sent:

Wednesday, August 21, 2013 10:55 AM

To:

Schulz, Susan; Haklar, James; Santella, Dennis

Subject:

Fw: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

From: Napolitano Philip < PNapolitano 2@schools.nyc.gov>

Sent: Wednesday, August 21, 2013 10:52:47 AM

To: Gorman, John

Subject: RE: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

I will have a list of schools for you by next week. Preliminary numbers look to be around 15 buildings.

From: Gorman, John [mailto:Gorman.John@epa.gov]

Sent: Wednesday, August 21, 2013 8:56 AM

To: Napolitano Philip

Subject: RE: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

Can you give me an estimate on when the list of buildings with PCB cabinets will be completed? How many schools have been identified so far that have PCB cabinets?



John Gorman, Chief Pesticides & Toxic Substances Branch USEPA Region 2 - Edison Facility Building 10 2890 Woodbridge Avenue Edison, NJ 08837-3679

732-321-6765 Fax: 732-321-6788 Cell: 908-420-4485 gorman.john@epa.gov www.epa.gov/region02

NOTICE: This communication may contain deliberative, confidential, attorney work product, or other enforcement-sensitive information. Do not release under FOIA without appropriate review. If this message was sent to you in error, you must delete it and not print, copy, re-transmit, disseminate, or otherwise use the information.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, August 19, 2013 10:21 AM

To: Gorman, John

Subject: RE: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

John,

As a follow up to my previous email, the PCB ballasts were removed from the cabinets. The impacted surface within the cabinets was cleaned by our environmental contractor and wipe samples were taken. The wipe test results are below the detection limit. We ventilated with fans and blower units.

The blowers (max rating 980 cfm) ran for over 24 hours in each of the hallways that are 4700 cuft. I used 700 cfm (in case the duct had a bend). $700 \text{ cfm } \times 1440 \text{ minutes} / 4700 \text{ cuft} = 214 \text{ air changes}$.

P.S. I am still working on a list of the other buildings that contain these types of ballast panels. I will keep you posted.

Regards, Phil

From: Napolitano Philip

Sent: Monday, August 05, 2013 9:55 AM

To: 'Gorman, John'

Subject: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

John:

I wanted to give you a heads up on some findings at P.S. 32 Staten Island located at 32 Elverton Avenue. This is one of a few buildings built in the 1960's that have ballast cabinets in the hallways. These ballasts provide the power to the light fixtures in the classrooms. The custodian inspected the hallway cabinets and found leaking PCB ballasts in cabinets on the 3rd and 2nd floors for a total of 3 cabinets. We are currently developing a plan of attack for ballast removal, cleaning, and testing. The school is closed for the summer. The cabinets may require cleaning, so I will keep you posted on any wipe sampling results. Here are some of the details:

2nd floor cabinet outside room 239: 6 leaking PCB ballasts, all are Universal 806 – BR. No manufacture date
3 Intact PCB ballasts, all are Magnetek 806-SLH-TC-P. No manufacture date

3rd floor cabinet outside room 310: 6 leaking PCB ballasts, all are Universal 806 – BR. No manufacture date 3 Intact PCB ballasts, all are Magnetek 806-SLH-TC-P. No manufacture date

3rd floor cabinet outside room 308: 4 leaking PCB ballasts, all are Universal 806 – BR. No manufacture date
2 intact PCB ballasts, Universal 806 – BR. No manufacture date
2 Intact PCB ballasts, Magnetek 806-SLH-TC-P. No manufacture date
1 leaking NON PCB ballast.

Regards, Phil

********************* ATTACHMENT NOT DELIVERED **************


This Email message contained an attachment named image001.jpg which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at $(866)\ 411-4$ EPA (4372). The TDD number is $(866)\ 489-4900$.

****** ***** ATTACHMENT NOT DELIVERED ****************



From:

Gorman, John

Sent:

Tuesday, August 20, 2013 4:11 PM

To: Subject: Schulz, Susan; Haklar, James; Santella, Dennis FW: P.S. 265 Brooklyn smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Tuesday, August 20, 2013 2:02 PM

To: Gorman, John

Subject: RE: P.S. 265 Brooklyn smoking ballast incident

John:

As a follow up to my previous email, 3 fixtures containing 1 leaking pcb ballast (smoke), and 2 non pcb ballasts was removed from room B3. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The room will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit. The school is currently undergoing a lighting upgrade.

The blower (max rating 980 cfm) has been running for over 48 hours in the room that is 3960 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 2880 minutes / 3960 cuft = 509 air changes.

Smoking ballast info:

Westinghouse

No manufacture date

No thermal protection

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Wednesday, August 07, 2013 11:20 AM

To: 'Gorman, John'

Subject: P.S. 265 Brooklyn smoking ballast incident

Good morning John:

P.S. 265 located at 101 Park Avenue in Brooklyn had a visibly smoking ballast in room B3 earlier today 8/7. The room was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture today. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent when student return from summer recess. The school is currently undergoing a building wide lighting replacement. I will update you once wipe sample results are returned.

Regards, Phil

From:

Gorman, John

Sent:

Monday, August 19, 2013 10:44 AM

To:

Schulz, Susan; Haklar, James; Santella, Dennis

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, August 19, 2013 10:21 AM

To: Gorman, John

Subject: RE: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

John,

As a follow up to my previous email, the PCB ballasts were removed from the cabinets. The impacted surface within the cabinets was cleaned by our environmental contractor and wipe samples were taken. The wipe test results are below the detection limit. We ventilated with fans and blower units.

The blowers (max rating 980 cfm) ran for over 24 hours in each of the hallways that are 4700 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 4700 cuft = 214 air changes.

P.S. I am still working on a list of the other buildings that contain these types of ballast panels. I will keep you posted.

Regards, Phil

From: Napolitano Philip

Sent: Monday, August 05, 2013 9:55 AM

To: 'Gorman, John'

Subject: P.S. 32 Staten Island Leaking ballast contained to an electrical panel.

John:

I wanted to give you a heads up on some findings at P.S. 32 Staten Island located at 32 Elverton Avenue. This is one of a few buildings built in the 1960's that have ballast cabinets in the hallways. These ballasts provide the power to the light fixtures in the classrooms. The custodian inspected the hallway cabinets and found leaking PCB ballasts in cabinets on the 3rd and 2nd floors for a total of 3 cabinets. We are currently developing a plan of attack for ballast removal, cleaning, and testing. The school is closed for the summer. The cabinets may require cleaning, so I will keep you posted on any wipe sampling results. Here are some of the details:

2nd floor cabinet outside room 239: 6 leaking PCB ballasts, all are Universal 806 – BR. No manufacture date

3 Intact PCB ballasts, all are Magnetek 806-SLH-TC-P. No manufacture date

3rd floor cabinet outside room 310: 6 leaking PCB ballasts, all are Universal 806 – BR. No manufacture date

3 Intact PCB ballasts, all are Magnetek 806-SLH-TC-P. No manufacture date

3rd floor cabinet outside room 308: 4 leaking PCB ballasts, all are Universal 806 – BR. No manufacture date
2 intact PCB ballasts, Universal 806 – BR. No manufacture date
2 Intact PCB ballasts, Magnetek 806-SLH-TC-P. No manufacture date

1 leaking NON PCB ballast.

Regards,				
Phil				
		시아 : 다 다 이 중 맛있음안! 연극		

From:

Gorman, John

Sent:

Monday, August 19, 2013 10:42 AM

To:

Schulz, Susan; Haklar, James; Santella, Dennis

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 78 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, August 19, 2013 9:12 AM

To: Gorman, John

Subject: RE: P.S. 78 Bronx smoking ballast incident

John:

As a follow up to my previous email, 1 fixture containing 1 leaking pcb ballast was removed from the 5th floor hallway. Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The hallway will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blower (max rating 980 cfm) ran for over 48 hours in the hallway that is 20,000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 2880 minutes / 20,000 cuft = 100 air changes.

Smoking ballast info was illegible due to heavy staining.

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Thursday, August 08, 2013 12:40 PM

To: 'Gorman, John'

Subject: P.S. 78 Bronx smoking ballast incident

John:

P.S. 78 located at 1400 Needham Avenue in the Bronx had a visibly smoking ballast in the 5th floor hallway today 8/8. The hallway was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The hallway will remain closed pending wipe sample results. Parent notification letters will be sent when students return from summer recess. I will update you once wipe sample results are returned.

Regards, Phil

Philip Napolitano

From: Gorman, John

Sent: Monday, August 19, 2013 10:41 AM

To: Schulz, Susan; Haklar, James; Santella, Dennis

Cc: Molnar, William; Wienckoski, Ronald

Subject: FW: Westinghouse H.S. K580 in Brooklyn leaking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, August 19, 2013 9:00 AM

To: Gorman, John

Subject: RE: Westinghouse H.S. K580 in Brooklyn leaking ballast incident

John:

As a follow up to my previous email, 1 fixture containing 1 leaking pcb ballast was removed from the office rm 142. The stain reported by the school was inspected by our environmental contractor and was determined to be non pcb in nature (possibly food or soda). Wipe samples were taken and have been returned. Sample results are below the federal action level of 10 ug/cm². The office will be re-occupied. Parent notification letters will be sent. We ventilated with a pedestal fan and blower unit.

The blowers (max rating 980 cfm) have been running for over 24 hours in the office that is 3000 cuft. I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 3000 cuft = 336 air changes.

Smoking ballast info:

Universal

No manufacture date

No thermal protection

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Monday, August 05, 2013 11:15 AM

To: 'Gorman, John'

Subject: Westinghouse H.S. K580 in Brooklyn leaking ballast incident

John:

Westinghouse H.S. located at 105 Johnson Street in Brooklyn had a leaking ballast in an office room 142 this morning 8/05. The room was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect and remove the fixture. There is a drop of fluid on a floor tile below the fixture. The impacted floor will be cleaned and wipe tested. The contractor will also provide additional ventilation with a blower unit. The

room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil

From:

Gorman, John

Sent:

Monday, August 19, 2013 10:40 AM

To:

Haklar, James; Schulz, Susan; Santella, Dennis

Cc:

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 42 Bronx four smoking ballasts incidents

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, August 19, 2013 8:07 AM

To: Gorman, John

Subject: RE: P.S. 42 Bronx four smoking ballasts incidents

John,

As a follow up to my previous email, the impacted floor was cleaned by our environmental contractor and 5 wipe samples were taken from room 305. All wipe sample results are below the detection limit. Room 305 will be re-occupied.

Regards, Phil

From: Napolitano Philip

Sent: Wednesday, July 31, 2013 3:28 PM

To: 'Gorman, John'

Subject: RE: P.S. 42 Bronx four smoking ballasts incidents

Good afternoon John:

As a follow up to my previous email, 3 fixtures were removed from room 106, they contained 1 intact PCB ballast, 1 leaking PCB ballast(smoke) and 1 NONPCB ballast with historical staining. 3 fixtures were removed from room 102, they contained 1 leaking PCB ballast(smoke), 2 NONPCB ballasts with historical staining. 3 fixtures were removed from room 209, they contained 2 leaking PCB ballasts (smoke), 1 NONPCB ballast with historical staining. 3 fixtures were removed from room 305, they contained 3 leaking PCB ballasts. Wipe samples were taken from the 4 rooms and have been returned. All sample results are below the federal action level of 10 ug/cm². One sample from the floor in room 305 was above the detection limit. Our environmental contractor will clean the area where the sample was taken and we will retest. Rooms 106, 102, 209 will be re-occupied. Parent notification letters will be sent once students return from summer recess. We ventilated each room with a pedestal fan and blower unit. I will update you on room 305 when the next set of results are returned.

Blowers (max rating 980 cfm) have been running for over 24 hours in each of the classrooms 9220 cuft(per room). I used 700 cfm (in case the duct had a bend). 700 cfm x 1440 minutes / 9220 cuft = 109 air changes.

Smoking ballast info

Room 106: GE, no date, no thermal protection

Room 102: GE, no date, thermally protected

Room 209: GE, no date no thermal protection

Room 305: Ballast info was not legible

Let me know if you have any questions

Regards, Phil

From: Napolitano Philip

Sent: Monday, July 29, 2013 3:35 PM

To: 'Gorman, John'

Subject: P.S. 42 Bronx four smoking ballasts incidents

John,

P.S. 42 located at 1537 Washington Avenue in the Bronx had four visibly smoking ballasts recently. One fixture each in room's 106 and 305 on 7/26. One fixture each in room's 102 and 209 today 7/29. The rooms were immediately secured. Fans were put in place to aid in ventilation. Fixture removal and wipe samples will be completed today. The environmental contractor will provide additional ventilation with a blower unit in each room. The rooms will remain closed pending wipe sample results. Parent notification letters will be sent when students return from summer recess. I will update you once wipe sample results are returned.

Regards

Phil

Philip Napolitano

Deputy Director of Facilities

NYC Department of Education

Division of School Facilities

44-36 Vernon Boulevard

Long Island City, N.Y. 11101

718 349 5583 tel

From:

Gorman, John

Sent:

Monday, August 19, 2013 10:38 AM

To: Cc:

Haklar, James; Schulz, Susan; Santella, Dennis

- . . .

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 150 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Monday, August 19, 2013 7:48 AM

To: Gorman, John

Subject: RE: P.S. 150 Bronx smoking ballast incident

Good morning John,

This report was a miscommunication. Our environmental contractor inspected the room and no issues were found.

Regards Phil

From: Napolitano Philip

Sent: Thursday, August 08, 2013 12:37 PM


To: 'Gorman, John'

Subject: P.S. 150 Bronx smoking ballast incident

Good morning John:

P.S. 150 located at 920 East 167th Street in the Bronx had a visibly smoking ballast in the AP office room 326 yesterday 8/7. The room was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Thursday, August 08, 2013 12:51 PM

To:

LaPosta, Dore

Cc:

Haklar, James; Schulz, Susan; Newton, Caroline; Santella, Dennis; Evangelista, Pat;

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 150 Bronx smoking ballast incident

Fifth reported failure at P.S. 150 in the Bronx.

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, August 08, 2013 12:37 PM


To: Gorman, John

Subject: P.S. 150 Bronx smoking ballast incident

Good morning John:

P.S. 150 located at 920 East 167th Street in the Bronx had a visibly smoking ballast in the AP office room 326 yesterday 8/7. The room was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The room will remain closed pending wipe sample results. Parent notification letters will be sent. I will update you once wipe sample results are returned.

Regards, Phil



From:

Gorman, John

Sent:

Thursday, August 08, 2013 12:49 PM

To:

LaPosta, Dore

Cc:

Haklar, James; Schulz, Susan; Santella, Dennis; Evangelista, Pat; Newton, Caroline;

Molnar, William; Wienckoski, Ronald

Subject:

FW: P.S. 78 Bronx smoking ballast incident

From: Napolitano Philip [mailto:PNapolitano2@schools.nyc.gov]

Sent: Thursday, August 08, 2013 12:40 PM

To: Gorman, John

Subject: P.S. 78 Bronx smoking ballast incident

John:

P.S. 78 located at 1400 Needham Avenue in the Bronx had a visibly smoking ballast in the 5th floor hallway today 8/8. The hallway was immediately secured. A fan was put in place to aid in ventilation. Our environmental contractor will inspect/remove the fixture tonight. They will also provide additional ventilation with a blower unit. Wipe samples will be taken as well. The hallway will remain closed pending wipe sample results. Parent notification letters will be sent when students return from summer recess. I will update you once wipe sample results are returned.

Regards, Phil

